

Internal Letter**Rockwell International**

WS-LT-00119

Date May 28, 1987

No DB 27.45

TO (Name Organization Internal Address)

Those Listed

FROM (Name Organization Internal Address Phone)

G. L. Potter
 HS&E Operations Mgt.
 Bldg. 123
 4283



000024624

SUBJECT REQUIRED ASSISTANCE FOR CLOSURE ACTIVITIES
 SURVEYING/RADIATION MONITORING/INDUSTRIAL HYGIENE

This letter is to notify departments of support activities required to complete some RCRA related Closure activities.

A number of areas at the Rocky Flats Plant require Closure under the RCRA regulations in order to protect human health and the environment. This process is a formally approved process regulated by the State of Colorado and the Federal EPA. The attached figures identify the outdoor sites undergoing Closure. The sites to be closed are: West Spray Field, PU&D Dumpster Storage Area, PU&D Drum Storage Area, Building 444/453 Drum Storage Area, S&W Building 980 Container Storage Facility, and the S&W Contractor Storage Yard.

All of these sites require some form of investigation conducted during this calendar year. The results from these investigations will be used to evaluate whether any further action is required to properly protect human health and the environment. These preliminary site activities must be completed before sample collection begins (July, 1987). Assistance will be required for some preliminary site work. Activities include but are not limited to:

- . delineation of areas for closure (Engineering)
 - stakes, flagging and/or roping off areas
 - only horizontal extent is required, no elevations need be shot
- . ground and ambient surveys for radioactivity and volatile organics (Radiation Safety and Industrial Hygiene)
 - radiation survey both alpha and gamma
 - organic survey with an Organic Vapor Analyzer, Flame Ionization Detector, or Photo-ionization Detector with direct calibration for trichloroethylene

Best Available Copy


ADMIN RECORD
 SW-A-000003

4/3 1/4

Those Listed
Page 2
May 28, 1987

DB 27.45


Frank Blaha will be contacting you as appropriate to schedule these activities. Additional information can be obtained from Frank at Ext.7041.



G. L. Potter, Manager
HS&E Operations Management

cc:
F. J. Blaha
G. W. Campbell
C. R. Lagerquist
J. D. Leigh
S. C. Sadler
G. H. Setlock
V. Terkun

2/3 2/4




Best Available Copy

LOCATION MAP

Fig. 1

PUAD DRUM STORAGE AREA

PUAD DUMPSTER STORAGE AREA



Best Available Copy